

- Site Report -

Date: April 5 2011

IRD Sales Order: 11167

To: Cindy Mantie From: Bryan Knight

Project Name/Location: LTPP AZ-1 US 93 N

Service Date(s): April 5 2011

Job Description: Maintenance Visit

Work Completed:

Recorded electrical readings of all in road sensors, Batteries, and Solar Panel output OK.

Logged onto WCU and monitored sensor performace OK.

 Performed visual inspection of road surface and inroad sensors OK. No unusual wear and tear noted.

Performed general housekeeping of equipment cabinet and filter.

6/19/96 IRD FORM No.: 1304A







702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9 Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>





Work Remaining: None

Schedule Include Estimate to Complete (on-track, ahead, behind):

Parts Used:

Pre-mature Equipment Failure:

Mileage / Travel Time: Total Travel: 1hr Total Onsite: 1hr

Safety Concerns:

Issues Related to Sub-Contractors:

Other Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		